

DRY STONE WORK

Fellowship Report



David Long

Master Builders Association of Victoria/
ISS Institute Fellowship

Fellowship funded by the
Master Builders Association of Victoria



ISS Institute

Suite 101
685 Burke Road
Camberwell Vic
AUSTRALIA 3124

Telephone

03 9882 0055

Facsimile

03 9882 9866

Email

issi.ceo@pacific.net.au

Web

www.issinstitute.org.au

Published by International Specialised Skills Institute, Melbourne.

ISS Institute
101/685 Burke Road
Camberwell 3124
AUSTRALIA

Also extract published on www.issinstitute.org.au

© Copyright ISS Institute 2003

This publication is copyright. No part may be reproduced by any process except in accordance with the provisions of the Copyright Act 1968.

Whilst this report has been accepted by ISS Institute, ISS Institute cannot provide expert peer review of the report, and except as may be required by law no responsibility can be accepted by ISS Institute for the content of the report, or omissions, typographical, print or photographic errors, or inaccuracies that may occur after publication or otherwise. ISS Institute do not accept responsibility for the consequences of any action taken or omitted to be taken by any person as a consequence of anything contained in, or omitted from, this report.

Table of Contents:

Acknowledgements	Page	2
Introduction	Pages	3-19
The Fellowship Program	Pages	20-41
Recommendations	Pages	42-47
Appendix 1 – Glossary of Terms	Pages	48-49
Appendix 2 – List of Reference Materials	Page	50
Appendix 3 – List of Supporting Documents	Page	51
Appendix 4 – A Special Note of Thanks	Page	52-53